

**ROBINSON
HELICOPTER COMPANY**

2901 Airport Drive, Torrance, California 90505

Phone (310) 539-0508 Fax (310) 539-5198

WED 14 JUNE 2000

VIA FAX


Mr. John R. Tarring
WORLDWIDE AVIATION LTD
UK
Fax: 011-44-120-257-7280

re: your June 12th 00 fax

Dear Mr. Tarring:

RHC has no objection to the using ACF-50 on R22- and R44-series helicopters. However, do not let it contaminate rod end Teflon-linings, friction clutch mechanisms, and main rotor hub bearings.

Sincerely,



Patrick Cox
Technical Support
ext 212